

## TECHNICAL DATA SHEET

Order No. 443-2102

Item/Model SARO Milkshake Mixer Double

model SOTUS 2

GTIN 4017337071838



- Material: stainless steel

- Includes 2 x 0.75 L stainless steel cups, separately switchable

- 4 non-slip feet

Connection: 230 V - 50 Hz - 2 x 0.08 kWDimensions: W 360 x D 170 x H 510 mm

- Weight (net/gross): 6.9 / 7.6 kg

Origin China customs tariff no. 84388091

Stand: 06.03.2025

Importer Saro Gastro-Products GmbH, Sandbahn 6, 46446 Emmerich am Rhein, GERMANY



## SAFETY & WARNING INSTRUCTIONS

Order No. 443-2102

Item/Model SARO Milkshake Mixer Double

model SOTUS 2

GTIN 4017337071838



## Safety and Warning Instructions

- Place the device only on a stable, level, and non-slip surface.
- Installation and repairs must only be performed by a qualified technician. Do not remove any components of the device without authorization.
- Children and unauthorized persons must not operate or be unsupervised near the device.
- During operation, there is a risk of injury from the rotating stirrers do not insert hands or objects into the mixing cup while the device is running.
- Never clean the device with a water jet or immerse it in liquids, as this poses a risk of short circuits and electric shock.
- Always switch off, unplug, and allow the device to cool completely before cleaning, maintenance, or extended non-use
- The device is intended exclusively for mixing beverages. Any other use may cause damage and compromise safety.
- Do not use damaged or loose stirrers. Replace damaged parts before using the device.

## - Milk can double in volume during mixing – fill the cup accordingly to avoid overflow.

- Dispose of packaging materials safely, as they may pose a choking hazard.
- The device is designed for commercial use and is not suitable for outdoor or wet environments.
- The mixing cup is not dishwasher-safe and should be cleaned with warm, soapy water.
- Repairs must only be carried out by qualified personnel using original spare parts.
- Regularly inspect the power cord for damage. A damaged cord must not be used and should be replaced by a professional.
- Do not leave the device unattended during operation.
- Immediately discontinue use if visible damage or malfunctions occur and contact qualified personnel.
- Use the device in accordance with the instructions in the user manual to ensure safe and efficient operation.

Origin China customs tariff no. 84388091

Stand: 06.03.2025

Importer Saro Gastro-Products GmbH, Sandbahn 6, 46446 Emmerich am Rhein, GERMANY